



INŽENJERSKA GRAFIKA

Metalurško-tehnološki fakultet
Univerzitet Crne Gore

Prof. dr Darko Bajić
2024.





Aksonometrijski prikaz objekta


- Kada je potrebno da se predmet prikaže prostorno, shvatljivo na jednom izgledu koristi se **aksonometrijsko prikazivanje**.
- Aksonometrija znači odmjeravanje po osama.
- Primjenom aksonometrijske projekcije elementa, ivice elementa koje su paralelne u prostoru ostaju paralelne i na crtežu.

Izometrijski prikaz elementa


Sve tri dimenzije prikazane su u istoj razmjeri.



Dimetrijski prikaz elementa






Kosa projekcija








- Kosa projekcija se koristi kada na čeonoj površini ima veliki broj kružnica, pa se crtaju kružnice i kružni lukovi, a ne elipse i eliptični lukovi.



IZOMETRIJSKI PRIKAZ OBJEKTA











































































Prof. dr Darko Bajić
Mašinski fakultet, Podgorica

Zahvalujem na pažnji!